Performance of highly alloyed materials in chlorination bleaching

Reprinted with permission from the

National Association of Corrosion Engineers, NACE, Corrosion/92, paper Nº 323

Houston, TX, 1992



NICKEL DEVELOPMENT INSTITUTE NiDI Reprint Series № 14 023

Arthur H. Tuthill and Donald E. Bardsley

The material presented in this publication has been prepared for the general information of the reader and should not be used or relied on for specific applications without first securing competent advice.

The Nickel Development Institute, its members, staff and consultants do not represent or warrant its suitability for any general or specific use and assume no liability or responsibility of any kind in connection with the information herein.

Performance of highly alloyed materials in chlorination bleaching

A. H. Tuthill
Consultant, P.O. Box 204, Blacksburg, VA U.S.A.

D. E. Bardsley
IMPCO Pulp Machinery Division, Ingersoll Rand, Nashua, NH U.S.A.

Abstract

Mills are currently increasing chlorine dioxide substitution to 50% and more in the chlorination stage in order to reduce dioxins. Re-examination of the Technical Association of the Pulp and Paper Industry (TAPPI) Phase II data base indicates that up to, at least 48% chlorine dioxide substitution there is no significant difference in alloy performance as determined in the Phase II evaluation program in bleach plant washer environments. Phase II data on localized corrosion replotted provides new and better guidelines on boundary conditions. Based on the wide range in pH, residual chlorine, temperature and chloride covered in these exposures it appears that the 6% Mo alloys can be expected to perform well except under the most extreme combinations of conditions. General corrosion rates for nickel base alloys in C stage do not exceed 0.2 mpy in the Phase II exposures, as compared to the 0.1-0.9 mpy in acidic D stage and 0.1-2.9 mpy in neutralized D stage environments. New data from the C stage of a short sequence bleach plant indicates that the nickel base alloys are useful as washers and piping. In C stage environments too aggressive for 6% Mo alloys, nickel base alloys perform well. The cast C4C and wrought C22 alloys are useful in high intensity mixers handling chlorine. Titanium is the preferred material for high intensity mixers handling the chlorine dioxide used in C stage. In some mills titanium is also used for the chlorine high intensity mixer with an elaborate interlock and alarm system to prevent dry chlorine from reaching the titanium.

Alloys And The Environment

Table I presents the composition and Unified Numbering System (UNS) numbers of the alloys mentioned in this paper.

Mills are currently pursuing a variety of programs aimed at reducing dioxins. Substitution of chlorine dioxide for 50% or more of the chlorine in C stage is a major trend most mills are adopting. *Table II* adds the % of chlorine dioxide substitution to the previously published Phase II data on C stage environments¹. Four of the eight mills were using substantial levels of chlorine dioxide substitution of 16,25,41 and 48 per cent. These data indicate that the conclusions on alloy performance in C stage already drawn and published

from the Phase II C stage data are valid up to, at least, 48% chlorine dioxide substitution.

Table I
Composition of Alloys

Behaviour of highly alloyed materials in C and C/D stage chlorination washer environments

Figure 1 plots the depth of pitting on the boldly exposed surface and the depth of crevice corrosion for three common stainless steels versus maximum residual chlorine, minimum pH, maximum temperature and chloride ion concentration as determined from the daily log sheets during the period of exposure. These Phase II data were previously published¹. Percent of chlorine dioxide substitution is also given. Crevice corrosion is shown to be the primary mode of corrosion which is in accordance with field experience. The increase in corrosion resistance with increasing Mo content is clear, which also corresponds with experience.

In 7 of the 8 mills the 6% Mo alloy meets the criteria for superior performance (<5 mills base plate pitting and <5 mills

| Common Name | UNS | Cr | Ni | Мо | Other | |
|-------------|--------|----|-----|-----|-------|--------------|
| 317L | S31703 | 18 | 14 | 3 | - | |
| 904L | N08904 | 21 | 26 | 4.5 | 2Cu | |
| AL-6XN® | N08367 | 21 | 25 | 6 | - | 0.2N |
| 254SMO® | S31254 | 20 | 18 | 6 | 0.7Cu | 0.2N |
| 1925hMO® | N08925 | 20 | 25 | 6 | 1.5Cu | 0.12N |
| 20Mo-6® | N08026 | 24 | 33 | 6 | 3Cu | |
| 25-6Mo® | N08926 | 20 | 25 | 6 | 0.8Cu | 0.2N |
| Alloy 625 | N06625 | 22 | 60 | 9 | - | |
| Alloy G | N06007 | 23 | 48 | 6.5 | 2Cu | • |
| Alloy G3 | N06985 | 25 | 50 | 6.5 | 1Cu | |
| Alloy C276 | N10276 | 16 | 58 | 16 | 4W | |
| C-22 Alloy | N06022 | 22 | 59 | 13 | 3W | |
| Cast C4C | N06455 | 16 | 65 | 16 | 2Fe | 1W |
| Ti Code 12 | R53400 | - | .08 | 0.3 | 0.08C | .03N Bal Ti2 |
| Ti Gr 2 | R50400 | - | - | - | 0.01C | .03N Bal Ti |
| | | | | | | |

® Registered Trademark

Alloy Product of:

AL-6XN Allegheny Ludlum Steel Corporation 20Mo-6 Carpenter Technology Corporation 1925hMo 254SMO Avesta Jernverks AB 25-6Mo

Alloy Product of:
925hMo VDM Technologies
5-6Mo Inco Alloys International

Table IIChlorination stage environments (TAPPI - Phase II)

| Mill Stage | EE D/C | AA D/C | FF C | CC C | BB C | DD D/C | GG D/C | JJ D/C |
|---|-----------|-----------|------|---------|---------|-----------|-----------|-----------|
| % Cl O ₂ Substitution | 16 | 48 | 0 | 0 | 0 | 0.33 | 25 | 41 |
| pН | | | | | | | | |
| Av. Daily Min | 2.0 | 1.9 | 1.6 | 2.0* | 1.4 | 2.0 | 1.4 | 2.1* |
| Av. Daily Max | 2.2 | 2.4 | 2.2 | | 1.6 | 2.7 | 2.2 | |
| Residual Cl, ppm | | | | | | | | |
| Av. Daily Min | 15 | 16 | 27 | 30* | 50 | 50 | 148 | 320 |
| Av. Daily Max | 1 | 8 | 2 | | 10 | 8 | 13 | 61 |
| Temperature -°F Temperature -°C (Av. Daily Max) | 103 | 137 | 103 | 105* | 114 | 98 | 138 | 109* |
| Chloride - ppm | 1500 | 5500 | 1900 | 1100 | 3500 | 1000 | 1500 | 1400 |




Figure 1 Depth of pitting in base plate and depth crevice corrosion - stainless steels - D/C & C stages.

crevice corrosion) established in ranking alloy resistance in earlier programs². In the one mill where the 6% Mo alloy failed to meet these criteria, the low pH (1.4) combined with the high residual (148ppm), high temperature (138F) and 1400 ppm chlorides results in a C stage environment that appears to be too aggressive for 6% Mo. In mill BB where the pH was also 1.4, but residual chlorine was moderate (50ppm) and in mill JJ where residual chlorine was higher (320ppm) but pH was higher (2.1), 6% Mo met the criteria for superior performance. The 6% Mo alloy appears to be useful in a wide range of C and C/D stage environments as long as very high residuals are not combined with very low pHs and high temperatures. Good experience with the 75 plus 6% Mo washers placed in service since 1982 tends to support the broad applicability of the 6% Mo alloys for bleach plant service that the Phase II data suggested.

Figure 2 plots the depth of pitting and crevice corrosion for three nickel base alloys versus residual chlorine, pH, temperature and chloride ion concentration. Data for alloy C276, UNS N10276, and the two titanium alloys was not plotted as there was no pitting or crevice corrosion on these alloys in any mill exposure. All four nickel base alloys and the two titanium alloys meet the criteria for superior service in all 8 mills. These 6 alloys appear to be good candidates for those few low




Figure 2 Depth of pitting in base palte and depth of crevice corrosion - nickel base alloys - D/C & C stages.

pH, high residual chlorine, high temperature conditions where the 6% Mo alloys may be marginal.

The general corrosion rates of alloys that were resistant to localized corrosion were not originally reported with the Phase II data as the most of the alloys suffered localized corrosion. To answer questions that have arisen about the general corrosion rates of the alloys that suffered little or no localized corrosion, the general corrosion rates of the four nickel base alloys and the two titanium alloys have been calculated and are shown in *Table III*.

Table IIIGeneral Corrosion rates -- Alloys resistant to localized corrosion Phase II Data

| Alloy | UNS No. | Corrosion rate mpy |
|-----------|---------|--------------------|
| G | N06007 | <0.1 in 8 mills |
| G3 | N06985 | <0.1 in 7 mills |
| | | 0.1 in 1 mill |
| 625 | N06625 | <0.1 in 7 mills |
| | | 0.2 in 1 mill |
| C276 | N10276 | <0.1 in 8 mills |
| TiCode 12 | R53400 | <0.1 in 8 mills |
| TiGr2 | R50400 | <0.1 in 8 mills |
| | | |

The periods of exposure varied from 6-7 months. Nickel base alloys exhibit negligible general corrosion rates of 0.1-0.2 mpy, and titanium alloys also exhibit negligible general corrosion rates in C and D/C stage environments up to, at least, 48% chlorine dioxide substitution. This compares with general corrosion rates of 0.1-0.9 mpy for nickel base alloy C276, in acidic D stage environments and with 0.1-2.9 mpy in long term exposures in neutralized D stage environments, Wensley and Reid report higher general corrosion rates ranging from 2.2 to 10.6 mpy for alloy C276, in short term tests³. The higher rates and the wide variation in general corrosion rates in Wensley and Reid's short term data are typical of general corrosion rates for alloys in the early period of protective film formation before the film is fully formed and fully protective.

Short sequence bleaching

In 1985, IMPCO started the first short sequence C/D - E/O - D low level bleach plant in North America at Mead Paper in Chillocothe, Ohio. This state-of-the-art technology utilized Compaction Baffle Filters and short sequence bleaching. The process operates with 20% chlorine dioxide substitution and a 145F temperature which is at the high end of the temperature range for current chlorination stage practice. The Compaction Baffle Filter, Figure 3, is completely sealed, containing the process liquid and vapor within the vat and hood. Coupon test racks were installed in the inlet box in the liquid and in the hood in the vapor zone. Results of a similar exposure in the chlorine dioxide stage at this mill were reported previously⁴.




Figure 3 Compaction baffle filter.

Preparation For field testing

Welded specimens of 317L (S31703), AL-6XN® (N08367), 254SMO® (S31254), 1925hMO® (N08925) and C22 (N06022) were prepared, pickled and assembled on a conventional test rack for exposure. Table IV shows the results and the environmental conditions during exposure.

Discussion – After 13 months in the inlet box where the pH averaged 1.7, temperature 145F, and residual chlorine a trace, base plate pit depth was 9 mils and crevice corrosion depth was 10 mils for 317L. The base plate of one the three 6% Mo alloys had a 3 mil deep pit and a 2 mil depth of crevice corrosion. There was no pitting of the base metal of the other two 6% Mo alloys, but there was 9 mils depth of crevice corrosion on each. The nickel base alloy C22 was free of localized corrosion on the base plate and in the creviced area. The general corrosion rate was <0.1 mpy. The 254SMO® washer in the chlorination stage at this mill was carefully inspected after 5 years service during a design update and found free of localized corrosion. This is consistent with earlier findings indicating that alloys perform somewhat better in the washer itself than specimens submerged in the liquor in the vat⁵.

In the vapor zone the base plate of the four stainless steels suffered substantial pitting and some crevice corrosion, whereas the nickel base alloy was completely resistant to localized corrosion. The general corrosion rate of the nickel base alloy in the vapor zone was <0.1 mpy as in the liquid phase.

Figures 4 and 5 show the comparative volume loss for the five alloys in the liquid and vapor phase.

Table IV Exposure in acidic chlorination stage of short sequence bleach plant. Volume loss - mm3 and maximum depth of attack - mils.

| | Inlet Box | Hood | |
|--|--|----------|----------------|
| рН | 1.5-2.0 | 1.5-2.0 | |
| | | 1.5-2.0 | |
| Cl ₂ ppm | 7 average | _ | |
| Temperature °F | 145 | 145 | |
| CI ppm | 1170-2750 | _ | |
| Exposure time | 13 months | 4 months | |
| S31703 3-4 mo | 20.2 | 260 | 142150 |
| BP | 9 | 35 | end are daring |
| CC A STATE OF THE | 10 | 12 | |
| N08367 6 Mo | 4.3 | 23.8 | |
| BP | 0 | 10 | |
| CC | 10 | 12 | |
| S31254 6 Mo | 4.2 | 60.1 | |
| BP | 0 | 23 | |
| CC | 9 | 7 | |
| | | | |
| N08925 6 Mo | 4.2 | 118.6 | |
| BP | 3 | 15 | |
| CC | 2 | 9 | |
| N06022 13 Mo | 1.2 | 1.0 | |
| BP | 0 | 0 | |
| CC AND A MATERIAL PROPERTY OF THE PARTY OF T | a de la companya de l | 0 | |
| CR - mpy | <0.1 | <0.1 | |

Alloy - Volume loss mm3 BP - Base plate pitting depth in mils

CC - Crevice corrosion depth in mils

CR - Mils per year corrosion rate




Figure 4 Chlorination inlet box (liquid phase) volume loss after 13 months exposure.




Figure 5 Chlorination hood (vapor phase) volume loss after 4 months exposure.

In other mills there has been some crevice corrosion on 6% Mo Compaction Baffle Washers in the area beneath the steam lift take-off under pulp pads which tend to accumulate in this area. Alloy C22 (N06022) has been used in this area successfully.


C Stage washer experience

A C22 washer was placed in service in an aggressive C stage in 1986. While no detailed inspection has been performed, operating forces have not encountered any problems. The washer is performing as would be anticipated from these data.

High intensity mixers

Alloys C4C (cast), C276 and C22, and commercially pure titanium are used in C stage high intensity mixers. For years nickel base alloys were preferred for the chlorine mixer because titanium is subject to pyrophoric reaction should dry chlorine come in contact with titanium. Titanium has been used for the chlorine mixer with the type of interlock and alarm system shown in Figure 6 to guard against dry chlorine reaching titanium during mill shutdown. Titanium is used for the chlorine dioxide mixer in those mills adding chlorine dioxide in the C stage. In a few mills chlorine and chlorine dioxide are mixed ahead of, or in the same mixer.

Historically, nickel base alloys have not performed well in chlorine dioxide mixers. In the late 1950s, commercially pure titanium was accepted as the preferred material of construction for mixers in this environment. Today, most mills are



Typical Interlock and Alarm System for Titanium Mixer used in Chlorination Service

- Flow control valve and #1 block valve to be interlocked with flow indicator switch
 in the mixer stock line to prevent flow control and #1 block valve from opening until
 mixer is full and stock is flowing.
- 2. Flush water timer activates when flow control valve is shut off as indicated by limit switch. SEQUENCE: Flush valves open for 10 seconds, then timer closes flush valve and #2 block valve and opens bleed valve. When system is ready to restart, operator will reset flush timer. This will close bleed valve and open #2 block valve. Flush valve remains closed.
- Surface temperature switch (set for 200°F/93°C) to monitor any titanium burning inside the mixer. Switch to shut off the flow control and #1 block valve which will then initiate the flush water timer. Switch to also trigger an alarm.

Figure 6 Interlocks to prevent dry chlorine reaching titanium mixer.

utilizing various levels of chlorine dioxide substitution in the chlorination environment, which has raised the question: "At what level of chlorine dioxide should titanium be used instead of a nickel base alloy?" IMPCO, the Pulp Machinery Division of Ingersoll-Rand Company, has undertaken an extensive study of various stainless steels, nickel base alloys and titanium in 100% chlorine, 100% chlorine dioxide and ten mixtures of chlorine and chlorine dioxide in order to develop data that will answer this question. The results from this research are scheduled for publication later this year.

Conclusions

- Previously published TAPPI Phase II corrosion data on the performance of alloys in C and D/C stage washers are valid for chlorine dioxide substitutions of, at least, 48%.
- Phase II data indicated 6% Mo alloys should perform well in C stage environments with high residuals unless the pH is unusually low and the temperature unusually high. However 6% Mo alloys are susceptible to significant base plate pitting in the vapor zone. Good experience with over 75 6% Mo washers in bleach plant service tends to support and confirm the data from specimen exposure programs on the wide applicability of 6% Mo alloys for bleach plant service.
- Titanium and nickel base alloys are resistant to localized corrosion and have very low general corrosion rates in C stage liquid and vapor zone environments. These materials are suitable for washers and piping in those mills where 6% Mo alloys may be marginal. Nickel base alloys are useful in high intensity mixers handling chlorine.
- Titanium is preferred for chlorine dioxide stage high intensity mixers and for chlorine dioxide mixers in C stage in those mills substituting chlorine dioxide for chlorine in C stage. Titanium has been used in chlorine stage mixers with interlocks to prevent dry chlorine reaching titanium during mill shutdowns.

References

- 1. A. H. Tuthill, "Corrosion in aggressive bleach plant environments results of Phase II exposure of 27 welded specimens in 19 United Sates and Canadian mills" TAPPI Engineering Conference, Dallas, TX, U.S.A., 1983.
 2. A. H. Tuthill, "TAPPI Phase II corrosion test program", Proceedings of The 4th International Symposium on Corrosion in the Pulp and Paper Industry, Stockholm, Sweden.
 3. D. A. Wensley and D. C. Reid, "Corrosion of nickel base alloys in chlorine Dioxide washer service", Corrosion/90 Las Vegas, NV, U.S.A., 1990.
- 4. A. H. Tuthill and D. E. Bardsley, "Performance of highly-alloyed materials in chlorine dioxide bleaching" TAPPI Engineering Conference, Seattle, WA, U.S.A., Sept. 1990. 5. A. H. Tuthill, "Comparison of test data and actual performance of 316L bleach plant washers" Materials Performance, 22 (7), pp. 45-51, July 1983.

The Nickel
Development
Institute is
an international
nonprofit
organization
serving the needs of
people interested
in the application of
nickel and
nickel-containing
materials.

Members of NiDI

Companhia Níquel Tocantins Empresa de Desenvolvimento de Recursos Minerals "CODEMIN" S.A. Falconbridge Limited Inco Limited Morro do Níquel S.A. Nippon Yakin Kogyo Co., Ltd. NRNQ (a limited partnership) Outokumpu Oy P.T. International Nickel Indonesia Pacific Metals Co., Ltd. **QNI Limited** Sherritt Inc. Shimura Kako Company, Ltd. Sumitomo Metal Mining Co., Ltd. Tokyo Nickel Company Ltd. Western Mining Corporation Limited

North America

Nickel Development Institute 214 King Street West - Suite 510 Toronto, Ontario

Canada M5H 3S6

Telephone 416 591-7999 Fax 416 591-7987 Telex 06 218 565

Europe

Nickel Development Institute 42 Weymouth Street London, England W1N 3LQ Telephone 071 493 7999 Fax 071 493 1555 Telex 51 261 286

Nickel Development Institute
European Technical Information Centre
The Holloway, Alvechurch
Birmingham, England B48 7QB
Telephone 0527 584 777
Fax 0527 585 562
Telex 51 337 125

Japan

Nickel Development Institute
11-3, 5-chome, Shimbashi
Minato-ku, Tokyo, Japan
Telephone
81 3 3436 7953
Fax
81 3 3436 7734
Telex
72 242 2386

Central & South America

Nickel Development Institute c/o Instituto de Metais Não Ferrosos Av. 9 de Julho, 4015, 01407-100 São Paulo-SP, Brasil Telephone 011 887 2033

Telephone 011 887 2033 Fax 011 885 8124 Telex 38 112 5479

India

Indian Nickel Development Institute c/o India Lead Zinc Information Centre Jawahar Dhatu Bhawan 39 Tughlaqabad Institutional Area Mehrauli-Badarpur Road New Delhi 110 062, India

Australasia

Nickel Development Institute P.O. Box 28, Blackburn South Victoria 3130, Australia Telephone 61 3 878 7558 Mobile 61 18 346 808 Fax 61 3 894 3403

South Korea

Nickel Development Institute Olympia Building, Room 811 196-7 Jamsilbon-Dong, Songpa-Ku Seoul 138 229, South Korea Telephone 82 2 419 6465 Fax 82 2 419 2088